



December 5, 2016

Our Ref.: 1400336

Texas Commission on Environmental Quality
MSW Permits Section, Waste Permits Division
P.O. Box 13087, MC-124
Austin, Texas 78711-3087

ATTN: Steve Odil

RECEIVED

DEC 07 2016

**WASTE PERMITS DIVISION
TEXAS COMMISSION ON
ENVIRONMENTAL QUALITY**

**RE: RESPONSE TO TCEQ NOTICE OF DEFICIENCY
PAA; PERMIT NO. MSW-692B
TEMPLE RECYCLING AND DISPOSAL FACILITY
BELL COUNTY, TEXAS
TRACKING NO. 20658545; CN605175884/RN100219401**

Dear Mr. Odil:

On behalf of the City of Temple, Golder Associates Inc. (Golder) submits this response to the Texas Commission on Environmental Quality's (TCEQ's) Notice of Deficiency (NOD) regarding the above-referenced PAA (PAA). TCEQ's NOD letter was dated on October 14, 2016.

The responses presented herein are cross-referenced to the NOD comments using the comment numbers in the NOD and quoting the original comments. We have also included an itemized list of the revised or new PAA pages.

One original and three (3) copies of the revised PAA materials and two (2) copy of the redline-strikeout revisions are included with this letter. The redline-strikeout revisions are organized per the order of the NOD comments. This response package will be posted to a publicly accessible website as indicated in the Part I form of the PAA.


We trust this response is sufficient to address the deficiencies identified by the TCEQ. Upon review of this response, if you have questions, please contact the undersigned at 281-821-6868.

Sincerely,

GOLDER ASSOCIATES INC.

May Xin, PE
Senior Engineer

Charles G. Dominguez, PE
Principal and Vice President



cc: Ms. Nicole Torralva, PE, Public Works Director, City of Temple
Mr. Steve Jacobs, Waste Management, Austin
Mr. Charles Rivette, Waste Management, Houston
Mr. David Mann, Waste Section Manager, TCEQ Region 9 Office